

## **NADCAP WAIVER REQUEST**

08/12/2016

**UTC Aerospace Systems** 

Four Coliseum Centre 2730 W. Tyvola Road Charlotte, NC 28217 Requestor's Name Dawn Mastin

Organization UTAS Central Supplier Quality

Address 2730 West Tyvola Rd

City, State Postal Code Telephone Charlotte, NC 28273 704-423-5814

Attn: Chris Reilly - Special Process Manager - special.processes@utas.utc.com

With this letter, FGP Systems Ltd located at Weymouth, Dorset, UK

Hereby requests a temporary waiver of the UTC Aerospace Systems Nadcap requirement to perform:

1. Repair – Conversion Coating per FEIS111 for UTAS Claverham transition product.

## Waiver Justification:

Business need for repair brush application only for Claverham transition.

## THIS SECTION TO BE COMPLETED BY UTC AEROSPACE SYSTEMS

The process approval was based upon on-site audit(s) performed by <a href="Dawn Mastin">Dawn Mastin</a> in accordance with UTAS-WRK-0003 and to Nadcap checklist **AC7108**, and **FEIS111** (attached to RAIL). **Check One:** 

- ☐ Supplier Accreditation Plan: The supplier has a plan for achieving Nadcap accreditation for the relevant processes. UTAS-FRM-0005 <u>Action Plan for Nadcap Accreditation</u> is attached. SBU has provided an interim risk mitigation plan.
- SBU Risk Mitigation Plan: (For suppliers not seeking accreditation, enter long-term plan {e.g. annual audits, move business})

No plans for Nadcap for this repair process. Audit has been done and actions closed. Supplier will be subject to periodic audits as required per UTAS Special Process Audit requirements.

## THIS SECTION TO BE COMPLETED BY UTAS CENTRAL QUALITY

Based on the above statements, indicate whether a temporary waiver can be granted and the expiry date of same.

**Waiver Granted Expiry Date**: *July* 31, 2019

☐ Waiver Denied - Please explain below.

TitleSignatureDateSite Requesting ManagerClaverham Limited8/12/2016CQ Special Process ManagerChris Reilly9/8/2016

Send to special.processes @utas.utc.com

